


Heli-Max™ **NOVUS**™ FP

Maintenance and Preflight Checks



It has been found that the two bolts shown above may come loose during normal use. To prevent this from occurring the following steps must be performed. Remove one bolt and apply thread locker to the screw (GPMR6060 Great Planes Pro Threadlocker is recommended). Reinstall and tighten the screw. Repeat the steps for the other screw.

Before each flight it is necessary to pre-flight the helicopter and check for loose screws, damaged parts or worn parts. This is a normal procedure that should be performed on all helicopters before flight. After a crash you must perform a thorough check of all parts to ensure that they have not been damaged.

Following these steps will help to ensure your enjoyment of the Heli-Max™ Novus FP radio controlled helicopter. Thank you for purchasing Heli-Max™ products.

If additional assistance is required for any reason,
please contact: **Product Support**
helihotline@hobbico.com
(217) 398-8970